


MOUNTING HOLE FOR #12-16 OR M4 SCREW

Blade Fuse Block

6Circuits

Wiring diagram



- Application Note:
1. The maximum rated current of battery box is 100A.
 2. Max. 30AMP per circuit