


Mechanical Hour Meter



Notice

1. Please pay attention to the safe use of electricity, to prevent electric shock.
2. Fix the hour meter by two screws in the front and a bracket from the back. Connect the pins to the external power. (can use the included spring and sheath)
3. Turn on the external power, the hour meter will make a sound of gears running, which means it is counting.

FEATURES

- 6 digits to display the total working hours
- High accuracy
- Low power consumption
- Wide range of supply voltage
- Wide operating temperature range
- Fits standard panel cut-out

PRODUCT ACCESSORIES LIST

1 Product*1	2 Box*1
3 User manual*1	4 Cushion rubber*1
5 6.3mm Insert spring*2	6 6.3mm Spring sheath*2
7 Mounting bracket*1	

SPECIFICATIONS

ITEM NAME	PARAMETERS
Hours range	0-99999.9H
Frequency	50/60Hz
Operating voltage	DC 6-80V AC 110-250V
Work temperature	-20°C to + 65°C
Error range	24H±10S
Working signal type	External power supply
Panel cut-out	43x39mm
Product size	φ59.5*53.2mm
Housing material	ABS
Weight	69g

PRODUCT DIMENSION

